

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated: .....

It is certified that the existing building ..... P.M. Shri. G.M.S.S.S. Pangna ..... (name of the building or premises) at Sub Tehsil Pangna Distt. Mandi (H.P.) .....

..... (address) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1) (Higher Sec) | Block (2) (EIE Block) | Block (3) (Admin)            | Block (4) | Block (5) | Block (6) |
|------------------------------|------------------------|-----------------------|------------------------------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | G+1                    | G+2                   | G+1 + 1 (Under Construction) |           |           |           |

The building is owned/occupied by ..... P.M. Shri. G.M.S.S.S. Pangna ..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ..... H.P.P.W.D. Karsoog ..... (Name of Department/ Govt.) on ..... 29/10/2025 ..... (date of inspection) in the presence of Sh. Sanjay Kumar Principal G.M.S.S.S. Pangna ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from ..... 29/10/2025 for a period of ..... 28/10/2026 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on ..... 29/10/2025 ..... at ..... Pangna ..... by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Executive Engineer  
Karsoog Division  
HP PWD Karsoog

Signature with Seal : .....  
Name : Assistant Engineer  
Designation : Pangna Sub Division  
Name & Address of Department/ Office: H.P.P.W.D. Pangna